



DISTRICT LABORATORY
GUJARAT JALSEVA TRAINING INSTITUTE
GUJARAT WATER SUPPLY & SEWERAGE BOARD
SECTOR - 15, 'G' Road, GANDHINAGAR - 382016



REPORT ON BACTERIOLOGICAL EXAMINATION OF WATER

Name & Address:-

Principal	Sender's Ref.No:	--
Kendriya Vidhyalaya No.1, Sector-30	Date of Receipt at Lab. / Arrival Date:	30-Jun-23
Gandhinagar	Sample Collected By:	Sender

Lab Ref. i.e. BW No.	728
Date of Collection	30-Jun-23
Date of Commencing Examination:	30-Jun-23
Source of Water Sample	R.O Water Kendriya Vidhyalaya No.1
Village	Gandhinagar
Habitation	Gandhinagar
Taluka	Gandhinagar
District	Gandhinagar
Membrane Filtration Method, IS-15185:2016, ISO 9308-1:2014 for Total Coliform	< 1
Membrane Filtration Method, IS-15185:2016, ISO 9308-1:2014 for Therotolerant Fecal Coliform (<i>E.coli</i>)	< 1
Opinion For Potability As Per The BIS:10500:2012	Safe

Important Note:-

- *Sample should be collected in sterile BOD bottle.
- **"Unsafe" :- Proper Disinfection may render it safe.
- *Presence of Coliform in water sample indicates the need of proper Disinfection.


NOTE :

- Table - 6 Bacteriological Quality of Drinking Water (BIS:10500:2012) : Second Revision.
- *All Water Intended for Drinking -
 - (a) *E.coli* or Thermotolerant coliform bacteria shall not be detectable in any 100ml sample.
- *Treated Water Entering the Distribution system & Treated Water in the Distribution system -
 - (a) *E.coli* or Thermotolerant coliform bacteria shall not be detectable in any 100ml sample.
 - (b) Total coliform bacteria shall not be detectable in any 100ml sample.

- 1) Test Report is issued for assessing Bacteriological Fitness as per the BIS 10500:2012 for the given Drinking Water Sample only.
- 2) This Report should not be taken as a basis to getting license from any Government authority.

Analysed By :
Microbiologist

S.B.Hadiya



Scientific Officer


PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

F.No:

Dated: 18 / 7 / 2023

It is certified that an inspection team headed by Dr. Brijesh Patel from
URBAN HEALTH CENTRE Palaj inspected the Kendriya Vidyalaya No.1, at
Sector-30, Gandhinagar on 15 / 7 / 2023 (date of inspection) and found that the Kendriya
Vidyalaya No.1, Sector-30, Gandhinagar(Gujarat) has safe drinking water facilities for the students and
members of staff of the institution and is maintaining the hygienic sanitation condition in the school
building & the campus as per norms prescribed by the State Govt.

The above is valid for a period of 1 Year.

Signature with seal: 
Name: Dr. Pooth G. Swami
Designation: MO
Name & Address of the Office / Department:

Medical Officer
Urban Health Centre
Palaj

To,
The Principal,
Kendriya Vidyalaya No.1,
Sector-30, Gandhinagar (Gujarat).